


IMPORTANT! Read entire instruction sheet before you start installation and assembly.


Parts List

Description	Qty	Part #
A mounting box	1	124-1841
B tilt bracket	1	200-1552
C M10 x 15mm penta-pin screw	8	520-9263
D penta-pin driver	1	520-9260
E u-bolt	2	560-1060
F nylock nut	4	530-9310
G flat washer	4	540-9454


NOTE: SOME PARTS MAY APPEAR SLIGHTLY DIFFERENT THAN ILLUSTRATED




A




B




E




C



D



F



G

⚠ WARNING

- Installer must verify that the ceiling will safely support the combined weight of all attached equipment and hardware.

- 1** Securely fasten mounting box (A) to support pipe (not included) using two u-bolts (E), four flat washers (G) and four nylock nuts (F).




fig 1.1

- 1-1** BY HAND, insert four M10 x 1.5 x 15 mm penta-pin screws (C) into threaded holes in the sides of ceiling arm box (A). Leave approximately 1/4" of exposed thread as shown in detail 1.





fig 1.2

Installation of Plasma Screens and 30" or Larger LCD Screens

NOTE: Refer to adapter plate instruction sheet for attachment of adapter plate to plasma before proceeding with step 2.

- 2** Attach tilt bracket (**B**) to adapter plate using four M10 x 15 mm penta-pin screws (**C**) in accordance with appropriate drawing below. Tighten using M10 penta-pin tool (**D**).



- 3** Hang tilt bracket (**B**) onto mounting box (**A**). Adjust tilt as desired and tighten four M10 x 1.5 x 15 mm penta-pin screws (**C**) securely using M10 penta-pin tool (**D**).

⚠ WARNING

- For a safe assembly be sure to fully tighten four screws (**C**).

